

LIST OF TABLES

| SERIAL NO. | LIST OF TABLES | PAGE NO. |
|------------|---|----------|
| Table 1.1 | Salient Features of the Project | 01-7 |
| Table 2.1 | Scoping Matrix for EIA Study for Dibang Multipurpose Project | 02-9 |
| Table 3.1 | Landuse Details of Directly Draining Catchment | 03-2 |
| Table 3.2 | Landuse of Submergence Area | 03-4 |
| Table 3.3 | Slope Details of Directly Draining Catchment | 03-4 |
| Table 3.4 | Features of R. Dibang Joining Major Tributaries (up to Dam Axis) | 03-8 |
| Table 3.5 | Precipitation Data | 03-10 |
| Table 3.6 | Observed Temperature and humidity data at Hunli | 03-12 |
| Table 3.7 | Observed Temperature and humidity data at Elopa | 03-12 |
| Table 3.8 | Categories and types of landslides encountered in the reservoir area of Dibang Multipurpose Project | 03-22 |
| Table 3.9 | Description of Landslides within the Reservoir Area of Dibang Multipurpose Project | 03-23 |
| Table 3.10 | Parameters of Fault Plane Solution Earthquakes | 03-36 |
| Table 3.11 | Water Sampling Report | 03-44 |
| Table 3.12 | Soil Details of Directly Draining Catchment | 03-46 |
| Table 3.13 | Soil Sample Analysis Report | 03-48 |
| Table 3.14 | Ambient Air Quality Test Report | 03-53 |
| Table 3.15 | Noise Quality Analysis Report | 03-54 |
| Table 4.1 | List of Gymnosperms | 04-35 |
| Table 4.2 | List of Pteridophytes | 04-35 |
| Table 4.3 | List of Bryophytes | 04-36 |
| Table 4.4 | List of Algae | 04-37 |
| Table 4.5 | List of Fungi | 04-37 |
| Table 4.6 | List of Mammals | 04-75 |
| Table 4.7 | List of Avi Fauna | 04-77 |
| Table 4.8 | List of Snakes and other Reptiles | 04-81 |
| Table 4.9 | List of Lizards | 04-82 |
| Table 4.10 | List of Amphibians | 04-82 |

| | | |
|------------|---|-------|
| Table 4.11 | List of Fish | 04-83 |
| Table 4.12 | List of Butterflies | 04-87 |
| Table 4.13 | List of Phytoplanktons, Zooplankton and Benthos | 04-88 |
| Table 4.14 | Status of Faunal Species as per Wildlife (Protection) Act, 1972 | 04-89 |
| Table 4.15 | Status of Faunal Species as per IUCN Red Data List 3.1 | 04-90 |
| Table 4.18 | Status of Fish as per National Bureau of Fish Genetic Resources | 04-90 |
| Table 5.1 | Demographic Profile of Arunachal Pradesh | 05-2 |
| Table 5.2 | Circle wise Demographic Details of Lower Dibang Valley | 05-4 |
| Table 5.3 | Circle wise Demographic Details of Dibang Valley District | 05-5 |
| Table 5.4 | Villages likely to be submerged | 05-6 |
| Table 5.5 | Details of Fully Affected Villages | 05-6 |
| Table 5.6 | Details of Partially Affected Villages | 05-7 |
| Table 5.7 | Land Requirement for the Project | 05-9 |
| Table 5.8 | Break-up of Land Requirement | 05-9 |
| Table 6.1 | Calculation of Muck to be Disposed of | 06-3 |
| Table 6.2 | Land required for the proposed Dibang Multipurpose Project | 06-5 |
| Table 6.3 | Noise level due to operation of various construction equipment | 06-16 |
| Table 6.4 | Increase in noise levels due to operation of various construction equipment | 06-16 |
| Table 6.5 | Transmission loss values for various construction materials | 06-17 |

LIST OF MAPS

| SERIAL NO. | LIST OF MAPS |
|------------|--|
| Map 1.1 | Layout Plan of Dibang Multipurpose Project |
| Map 3.1 | Land use map of the directly draining catchment |
| Map 3.2 | Land use map of submergence area |
| Map 3.3 | Slope map of directly draining catchment |
| Map 3.4 | Soil map of Directly Draining Catchment |
| Map 3.5 | Land Capability Classification of Dibang Catchment |
| Map 3.6 | Relief map of Dibang Catchment |
| Map 3.7 | Drainage network Map of Dibang Catchment Area |
| Map 3.7A | Drainage Map of Directly Draining Catchment showing Submergence area |
| Map 3.7B | Aspect Map of Directly Draining Catchment |
| Map 3.8 | Seismo-tectonic Map of India |
| Map 3.9 | Sampling sites of water, soil, air and Noise |
| Map 6.1 | Location of Wildlife Sanctuaries |

LIST OF FIGURES

| SERIAL NO. | LIST OF FIGURES | PAGE NO. |
|------------|----------------------------|----------|
| Fig. 3.1 | Tectonic Map of North East | 03-34 |
| Fig. 3.2 | Earthquake epicentre | 03-40 |

LIST OF PHOTOS

| SERIAL NO. | LIST OF PHOTOS | PAGE NO. |
|-------------------|---|-----------------|
| Photo 3.1 | Feldspathic biotite gneiss outcrop on the left bank near cane-bridge, downstream of the confluence of Ichi nala with Dibang | 03-19 |
| Photo 3.2 | Active landslide zone near Airi Pani confluence with Dibang river (about 2 km u/s of Dam axis) | 03-27 |
| Photo 3.3 | Active landslide zone (more than 1.5 km in extent) downstream of Kronli in the rocks of Hunli Formation | 03-28 |
| Photo 3.4 | Active landslide zone, left bank of Dibang at the confluence of Ithun and Dibang river | 03-28 |
| Photo 3.5 | Landslides on left bank of Dibang about 1.2 km downstream of Enne nala. High rate of toe erosion and failure along weak planes has made this slide active | 03-29 |